

Colmworth Rights of Way Issues

CROW Issue #	Source	Date Input	RoW number	Description	Contact	BBC Issue #	Comments/Action Required	Date Completed	Open/Closed	Map link	Image	Image
1	LK	30/09/2015	FP4	Footpath finger point between West View and Medlock, Lt Staughton Road	Francine Rainbow		Needs replacing	ongoing	Open	Map	No image	
2	LK	30/09/2015	Boat 25/FPA3	post and pointer on Church Road needs replacing (Finger pointer missing) Rotting post	Francine Rainbow		Needs replacing	ongoing	Open	Map	No image	
3	LK	30/09/2015	FPA3	Chapel Lane Finger post at FPA3 Obscured by hedge	Francine Rainbow		Hedge needs Cutting peggy	ongoing	Open	Map	No image	
4	LK	30/09/2015	FPA8	COLA8A Finger post Lt Staughton Rd/City Lane Overgrown by hedge	Francine Rainbow		Finger post at Lt Staughton Road/City Lane entrance is obscured by overgrown hedge - inform Footpaths	ongoing	Open	Map	Hover for image	
5	DM	10/02/2016	FPA8	Section of COLA8B in field after Meadowview is overgrown But path is on edge of field This has been reported since October 2015			Path needs mowing / hedge needs trimming			Map	Hover for image	
6	DM	10/02/2016	FPA8	Cross Field path sections COAL8B and COLA8C Have not been reinstated since ploughing and seeding			Path needs reinstating by farmer			Map	Hover for image	
7	DM	10/02/2016	FP1	Cross Field path sections COL1A and COL1B Have not been reinstated since ploughing and seeding			Path needs reinstating by farmer			Map	Hover for image	
8	MM	10/02/2016	BW3	Edge of field bridleway COL3B at the end of shelford lane track towards BW59 too narrow in parts Grass needs cutting Has rabbit hole						Map	Hover for image	Hover for image
9	MM	10/02/2016	BW59	Edge of field bridleway BK59B Hedge needs trimming Has Rabbit hole activity on hedge line			Hedge needs trimming			Map	No image	
10	MM	10/02/2016	BW59	Edge of field bridleway BK59B Waymaker has disk Missing			New waymaker disk needed			Map	Hover for image	
11	HS	10/02/2016	FP19	Cross field path COL19E Has not been reinstaed since ploughing and seeding. This is a regular occurence			Path needs Reinstating by Farmer			Map	Hover for image	
12	HS	10/02/2016	FP5	Cross field path COL5A Has not been reinstaed since ploughing and seeding. This is a regular occurence			Path needs Reinstating by Farmer			Map	Hover for image	
13	HS	10/02/2016	FP10	Cross field path COL10A Has not been reinstaed since ploughing and seeding. This is a regular occurence			Path needs Reinstating by Farmer			Map	No image	
14	HS	10/02/2016	FP26	Cross field path COL26A Has not been reinstaed since ploughing and seeding. This is a regular occurence			Path needs Reinstating by Farmer			Map	No image	
15	HS	10/02/2016	FP19	Cross field path COL19D Has not been reinstaed since ploughing and seeding. This is a regular occurence			Path needs Reinstating by Farmer			Map	No image	
16	MM	10/02/2016	FP42	Footpath ROT42A finger sign missing at Mill Rd			New Finger sign needed			Map	Hover for image	
17	MM	10/10/2015	FP23	Footpath COL23A for its entirety north of Begwary Brook bordering the woods its impassable	Dominique		Party needs sending	ongoing	open	Map	Image to follow	
18	CPC	10/10/2015	FP10	Surface mud floods problems	Dominique		Entrance to Park needs surface	ongoing	open	Map	No image	
19	CROW	18/10/2015	BridleVerges	To initiate to make Road side verge refuge for walkers and horses	Phil Fox		Initially looking at Wilden Rd/Chequers Hill although its a tricky spot initial walk revealed it could be beneficial	ongoing	open	Map	Phil took photos	